EXHIBIT 1

09-50026-mg Doc 13027-1 Filed 12/16/14 Entered 12/16/14 17:20:07 Exhibit 1 Pg 2 of 2

TECHNICAL ASSISTANCE CENTER

**** GM RESTRICTED ****

			,·,
	06589282	TITAT	· Deitropie
Lace No.	UD304202	1/ 1/\(\cdot\)	' Privacy :
Cuse IVO.	00007202	V 11 V.	i

Date Opened: 20030701 Model Year: 2003

Date Closed: 05/12/2014 Model Series: AZ

Dealer Code: ?152008 Mileage: 003205

Dealer Name: Kelly Saturn, Inc. Easton Dealer State: PA

Dealer Phone: 6107461800 Division: Saturn - GM

SYMPTOM ABSTRACT---- STALL ENGINE INT STALL P1599

RESOLUTION ABSTRACT-

UCC CODE 1-----

UCC-1 DESCRIPTION--- Engine

UCC CODE 2-----

UCC-2 DESCRIPTION---

UCC CODE 3-----

UCC-3 DESCRIPTION---

07/01/2003 14:05:00 SBD Template - KICKIRILLO

tech unable to duplicate. cust able to restart immediately. occurs at highway speed 2X.

advise tech to check P1599 failure record - note this is a manual trans.

advised tech to check connections at ecm and ei module. check ign switch. try to duplicate and check fuel pressure.

07/01/2003 14:05:00 History - KICKIRILLO

08/20/2003 15:03:44 REYNOLDS - closing

tech could not duplicate..

closing.